# Oil Field Environmental Incident Summary

Responsible Party: T & R Trucking

Well Operator: HRC OPERATING, LLC Well Name: GREV 157-100-30B-31-2H & 3H

Field Name: MARMON Well File #: 26118

Date Incident:7/24/2014Time Incident:12:00Facility ID Number:County:WILLIAMSTwp: 157Rng: 100Sec: 19Qtr:

Location Description: Constructed Well Site

Submitted By: Kelly Grimm Received By:

Contact Person: Soren Bostad

12125 ND HWY 5 Crosby, ND 58730

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:1.2 MileDistance Nearest Water Well:1.2 Mile

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 1 Barrels 1 Barrels

Other

Description of Other Released Contaminant:

NA

Inspected: Written Report Received: Clean Up Concluded:

#### Risk Evaluation:

No immediate risk to human health. Environmental impact limited to secondary containment, tanks and scoria/gravel

#### Areal Extent:

All contained on location within secondary containment

# Potential Environmental Impacts:

Impact to constructed well site scoria/topsoil

## Action Taken or Planned:

Monitor tank levels

Wastes Disposal Location: E&P approved disposal

Agencies Involved:

## **Updates**

Date: 7/25/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

## Notes:

Release, due to a tank overflow, remained on location within the diking according to the report. NDIC retains oversight.